METAL PRIMER AQUA PRIME #15 MSDS

MATERIAL SAFETY DATA SHEET

SECTION I PRODUCT IDENTITY: AQUA PRIME #15 ~ DTM METAL PRIMER

NAME: HY-TECH INDUSTRIES

CORPORATION

ADDRESS: P.O. Box 216 CITY, STATE AND ZIP CODE: Melbourne,Fl 32902 DATE OF PREPARATION: May 1999

INFORMATION TELEPHONE NO.: (321)

956-7728

For Emergency Assistance involving chemicals call

CHEMTREC (800) 424-9300

SECTION II - Hazardous Ingredients/Identity Information

HAZARDOUS COMPONENT	CAS. NO.	OSHA PEL OR ACGIH TLV	WEIGHT %			
*Propylene Glycol	57-55-6	100 PPM	0 - 3%			
* Indicates toxic chemical (s) subject to the reporting requirements of section 313 of Title III and or 40 CFR 372						

NOTE: Products contain no mercury or lead. These products may contain titanium dioxide, bentonite clays or other pigments which are hazardous only as dust when product is sanded. These products contain ingredients considered to be trade secrets by Hy–Tech Industries. This MSDS does, however disclose all necessary information needed to handle and use the product safely.

SECTION III – Physical/Chemical Characteristics

Boiling Points of Major Constituent: (Water)	212 F	Specific Gravity (H20=1) W	G/GAL	varies w/color
Vapor Pressure (mm Hg) @ 100 C	760	Melting Point Water (Ice)	Above	32 F
Vapor Density (AIR=1)				
Heavier	x	Evaporation Rate (Butyl Acetate=1)		Slower
Lighter				
Solubility in Water	Total	Appearance and Odor		Viscous liquid slight ammonia odor

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

Non-Flammable

Flash Point:	Flammable Limits:	DOT Hazard Class:	Marking: "Keep
Non-Combustible	LEL:N/A EUL: N/A	Not Regulated	from Freezing"

SPECIAL FIREFIGHTING PROCEDURES

Full protective equipment, including self-contained breathing apparatus, to be worn. Water should be used to cool closed containers to prevent explosion due to extreme heat.

SECTION V – REACTIVITY DATA

HAZARDOUS POLYMERIZATION: Will not occur

STABILITY: Stable

INCOMPATABILITY: Avoid Contact with: Strong oxidizing agents (e.g., nitric acid,

permanganates), etc.

HAZARDOUS DECOMPOSITION PRODUCTS: Some carbon monoxide

SECTION VI – HEALTH HAZARD DATA, TOXICITY DATA:

METAL PRIMER AQUA PRIME #15 MSDS

Route (s) of Entry: N/A Carcinogenicity? SEE NOTE IN PART II (ABOVE)

Health Hazards (Acute and Chronic)

EFFECTS OF OVEREXPOSURE: Inhalation, Vapors or spray mists may be slightly irritating to eye, nose, throat, and mucous membranes of respiratory tract producing symptoms of headache, nausea in poorly ventilated areas. Skin Contact: Prolonged or repeated contact with coating may cause slight skin irritation. Eye Contact: Direct contact: inconsequential eye irritation.

EMERGENCY AND FIRST AID PROCEDURES: Eye and skin Contact; Immediately flush eye with plenty of water for at least 15 minutes and consult physician; wash skin thoroughly with soap and water; if drenched, remove and wash clothing before reuse. Ingestion: If victim is conscious, give 2 glasses of water. Call a physician.

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Keep unnecessary people away. Floor may be silppery; use care to avoid falling. Dike and contain material with inert material (e.g. sand, earth). Transfer liquid to containers for recovery or disposal and solid diking material to separate containers for disposal. Keep spills and cleaning run–offs out of municipal sewers and open bodies of water.

WASTE DISPOSAL METHOD: The coating and any contaminated diking material should be thoughly air dried and collected into drums. The drums should then be sealed and properly labeled with waste designation and landfill or incinerated according to current local, state and federal regulations.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Maximum storage temperature 100 degrees Fahrenheit. Keep closure tight and container upright to prevent leakage. Precautionary Labeling: "Keep from Freezing".

OTHER PRECAUTIONS: Do not get in eyes. Avoid skin contact. Prevent prolonged or repeated breathing of vapor or spray mists. Do not handle until the manufacturer's safety precautions and label instructions have been read and understood. Avoid breathing sanding dust.

SECTION VIII – CONTROL MEASURES

RESPIRATORY PROTECTION: None required if good ventilation is maintained. Wear respirator (MSHA/NIOSH – approved or equivalent) suitable for concentrations and types of air contaminants encountered. Use approved chemical/mechanical filters designed to remove particulates in open and restricted ventilation areas. Use MSHA/NIOSH – approved airline type respirators or hood in confined areas.

VENTILATION: Sufficient ventilation, in pattern and volume, should be provided to keep the air contaminant concentration below applicable exposure limits. All application areas should be ventilated in accordance with OSHA regulation 29CFR Part 1910.94.

PROTECTIVE GLOVES: Impervious gloves should be worn if prolonged skin contact is likely. Use neoprene or rubber gloves to prevent prolonged skin contact.

EYE PROTECTION: Use safety eyewear including side shields, face shields, or chemical splash goggles (ANSIZ–87.1 or approved equivalent).

OTHER PROTECTIVE EQUIPMENT: Use disposable or impervious clothing if work clothing contamination is likely. Use protective cream if prolonged skin contact is likely.

METAL PRIMER AQUA PRIME #15 MSDS

HYGIENIC PRACTICES: Wash hands before eating, smoking or using the restroom. Food or beverages should not be consumed anywhere this product is being applied.

SECTION IX – DISCLAIMER

All information, recommendations and suggestions concerning this product are based upon tests and data believed to be reliable, Hy–Tech Industries makes no guarantee, expressed or implied, as to the effect of use, or the safety and toxicity of the product. The information contained in this sheet is not to be construed as absolutely complete.

REFERENCES:

- 1. Sax, N.I., "Dangerous Properties of Industrial Materials", 8th ed., Van Nostrand Reinhold Company Inc., NY, 1992.
- 2. American Conference of Governmental Industrial Hygienists, "TLV's and Biological Exposure Indices" for the current year (published annually).
- 3. U.S. Code of Federal Regulations (CFR) U.S. Dept. of Labor, No. 29, Parts 1900 to 1910.1200. OSHA Communications Standard 29 CFR 1910.1200.
- 4. Sax, N.I., R.J. "Hazardous Chemicals Desk Reference", Van Nostrand Reinhold Co., Inc., NY, 1987.
- 5. Fire Protection Guide to Hazardous Materials, 10ed., National Fire Protection Association, Quincy, MA, 1991.
- 6. Title III List of Lists, U.S. Environmental Protection Agency publication EPA 560/4–90–011, January 1990.